



















A1	x2		
A2	x2	A3	x2
A4	x2	A5	x8
A6	x4	A7	x4
A8	x4	A9	x14
A10	x2	A11	x1





- | | | | |
|---|--|--|--|
|  M5x14 (x4)
M-A |  M6x14 (x4)
M-B |  M8x20 (x4)
M-C |  M8x30 (x4)
M-D |
|  M8x30 (x4)
M-E |  washer (x4)
M-F |  small spacer (x8)
M-G |  big spacer (x4)
M-H |



2

